Verification Report

No.: NGBEC26003491401 **Date:** Jun 25, 2026

Client Name: ZHEJIANG TOT ELECTRIC CO.,LTD.

Client Address: NO.1, DEXIAN ROAD, CHENGNAN INDUSTRIAL ZONE, DONGHUA STREET, LONGYOU COUNTY, ZHEJIANG PROVINCE

Sample Name: Flush type socket-outlet with USB Power board

Tested Basic Model No.: E08T228-FW

Tested Extended Model No.: E08T236-FW

Client Ref. Information: abT228cd,abT236cd;
(ab=E01,E02,E03,E05,E06,E07,E08,E09,E10,E11,E12,E13,E14,E15,E16,E17, F01,F02,F02,F03,F04,F05,F06,F07,F08,F09,F10;
E01,E02,E03,E07,E08,E11,E12,E13,E14,E15,E16,E17,F01,F02,F03,F04,F05, F06,F07,F08,F09,F10 indicate white PC panel; E05, E09 indicateglass panel; E06, E10 indicate Aluminum panel; cd=blankor-SL,-BK,-CG,-SG, -BL, -BR, -WH, -RD,-MO, -CH, -IV,-GR,-BE,-FW,-FBK,-FBL,-FSL,-FBR,-FCG,-FSG,-FMK,-FSA,-FCR,-FTI,-FGU,-FPA,-MSL,-MBK,-MCG,-MBR,-MSG,-MRD,-GMO,-GCH,-GBE,-GWH,-GBK,-GCG,-GBL,-GSG-GRD: it indicates different color

The above sample(s) and information were provided by the client.

SGS Job No.: NBP26-003558

Sample Receiving Date: May 06, 2026

Verification Period: May 06, 2026 ~ Jun 09, 2026

Verification Requested: With reference to RoHS Directive (EU) 2015/863 amending 2011/65/EU.

Verification Method(s): Please refer to next page(s).

Verification Result(s): Please refer to next page(s).

Test Result Summary:

Test Items	Conclusion
EU RoHS Directive (EU) 2015/863 amending Annex II to Directive 2011/65/EU - Lead, Mercury, Cadmium, Hexavalent chromium, Polybrominated biphenyls (PBB), Polybrominated diphenyl ethers (PBDE), Bis(2-ethylhexyl) phthalate (DEHP), Butyl benzyl phthalate (BBP), Dibutyl phthalate (DBP) and Diisobutyl phthalate (DIBP)	Pass

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Hedy Hu
Approved Signatory

Scan to see the report

F4768BCB

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，006幢5号楼4层2区，008幢7号楼1层6区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Photo of Submitted Sample



E08T228-FW



E08T236-FW

Verification Method(s):

1. With reference to IEC 62321-2:2021, disassembly and disjointment were performed for the submitted samples.
2. With reference to IEC 62321-1:2013, tests were performed for the samples indicated by the photos in this report.
   (1) With reference to IEC 62321-3-1:2013, screening by EDXRF spectroscopy.
   (2) Wet chemical test method: With reference to IEC 62321-4:2013+A1:2017, IEC62321-5:2013, IEC

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab (CCL)

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区，5区 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

62321-7-1:2015, IEC 62321-7-2:2017, IEC 62321-12:2023, IEC 62321-6:2015 and IEC62321-8:2017 , analyzed by ICP-OES,UV-Vis and GC-MS.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Verification Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0034914-0001.C001	E08T228-FW-White plastic
SN2	A2	NGB26-0034914-0001.C002	E08T228-FW-White plastic
SN3	A3	NGB26-0034914-0001.C003	E08T228-FW-Silvery metal screw
SN4	A4	NGB26-0034914-0001.C004	E08T228-FW-Silvery metal spring
SN5	A5	NGB26-0034914-0001.C005	E08T228-FW-Silvery metal
SN6	A6	NGB26-0034914-0001.C006	E08T228-FW-Silvery metal
SN7	A7	NGB26-0034914-0001.C007	E08T228-FW-Silvery metal screw
SN8	A8	NGB26-0034914-0001.C008	E08T228-FW-Silvery metal
SN9	A9	NGB26-0034914-0001.C009	E08T228-FW-Golden metal
SN10	A10	NGB26-0034914-0001.C010	E08T228-FW-Golden metal
SN11	A11	NGB26-0034914-0001.C011	E08T228-FW-Gray plastic
SN12	A12	NGB26-0034914-0001.C012	E08T228-FW-Golden metal
SN13	A13	NGB26-0034914-0001.C013	E08T228-FW-Green PCB body
SN14	A14	NGB26-0034914-0001.C014	E08T228-FW-Silvery metal soldering tin
SN15	A15	NGB26-0034914-0001.C015	E08T228-FW-Silvery metal
SN16	A16	NGB26-0034914-0001.C016	E08T228-FW-Black plastic
SN17	A17	NGB26-0034914-0001.C017	E08T228-FW-Silvery metal
SN18	A18	NGB26-0034914-0001.C018	E08T228-FW-White plastic
SN19	A19	NGB26-0034914-0001.C019	E08T228-FW-Silvery metal pin
SN20	A20	NGB26-0034914-0001.C020	E08T228-FW-Green PCB body
SN21	A21	NGB26-0034914-0001.C021	E08T228-FW-Silvery metal soldering tin
SN22	A22	NGB26-0034914-0001.C022	E08T228-FW-Black plastic sheath
SN23	A23	NGB26-0034914-0001.C023	E08T228-FW-Brown plastic
SN24	A24	NGB26-0034914-0001.C024	E08T228-FW-Black rubber
SN25	A25	NGB26-0034914-0001.C025	E08T228-FW-Black plastic
SN26	A26	NGB26-0034914-0001.C026	E08T228-FW-Black rubber
SN27	A27	NGB26-0034914-0001.C027	E08T228-FW-Black rubber
SN28	A28	NGB26-0034914-0001.C028	E08T228-FW-Blue capacitor body
SN29	A29	NGB26-0034914-0001.C029	E08T228-FW-Transparent yellow plastic adhesive tape
SN30	A30	NGB26-0034914-0001.C030	E08T228-FW-Black plastic
SN31	A31	NGB26-0034914-0001.C031	E08T228-FW-Semitransparent plastic sheath
SN32	A32	NGB26-0034914-0001.C032	E08T228-FW-Black plastic sheath
SN33	A33	NGB26-0034914-0001.C033	E08T228-FW-Black rectifier bridge body
SN34	A34	NGB26-0034914-0001.C034	E08T228-FW-Black rectifier bridge body
SN35	A35	NGB26-0034914-0001.C035	E08T228-FW-Green PCB body
SN36	A36	NGB26-0034914-0001.C036	E08T228-FW-Silvery metal soldering tin
SN37	B1	NGB26-0034914-0002.C001	E08T236-FW-White plastic
SN38	B2	NGB26-0034914-0002.C002	E08T236-FW-Gray plastic
SN39	B3	NGB26-0034914-0002.C003	E08T236-FW-Silvery metal
SN40	B4	NGB26-0034914-0002.C004	E08T236-FW-Golden metal
SN41	B5	NGB26-0034914-0002.C005	E08T236-FW-Gray plastic

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Verification Result(s):

In accordance with the result of material risk assessment, the following disjointed parts in the submitted sample have been verified. (Unless otherwise specified, the unit is mg/kg).

Test Item(s)	A1	A2	A3	A4	A5	A6	A7	A8
Pb	BL	BL	BL	BL	BL	BL	ND	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	ND	BL	BL	BL	ND	BL	BL	BL
PBB	BL	BL	---	---	---	---	---	---
PBDE	BL	BL	---	---	---	---	---	---
DEHP	BL	BL	---	---	---	---	---	---
BBP	BL	BL	---	---	---	---	---	---
DBP	BL	BL	---	---	---	---	---	---
DIBP	BL	BL	---	---	---	---	---	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A9	A10	A11	A12	A13	A14	A15	A16
Pb	BL	62	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	ND	BL	BL	BL	BL
PBB	---	---	ND	---	BL	---	---	BL
PBDE	---	---	ND	---	BL	---	---	BL
DEHP	---	---	BL	---	BL	---	---	BL
BBP	---	---	BL	---	BL	---	---	BL
DBP	---	---	BL	---	BL	---	---	BL
DIBP	---	---	BL	---	BL	---	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A17	A18	A19	A20	A21	A22	A23	A24
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	ND	BL	BL	BL	BL	BL
PBB	---	BL	---	BL	---	BL	ND	BL
PBDE	---	BL	---	BL	---	BL	ND	BL
DEHP	---	BL	---	BL	---	ND	ND	BL
BBP	---	BL	---	BL	---	ND	ND	BL
DBP	---	BL	---	BL	---	ND	ND	BL
DIBP	---	BL	---	BL	---	ND	ND	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
PBB	BL	BL	BL	BL	BL	BL	ND	BL
PBDE	BL	BL	BL	BL	BL	BL	ND	BL
DEHP	ND	ND	ND	BL	BL	BL	ND	ND
BBP	ND	ND	ND	BL	BL	BL	ND	ND
DBP	ND	ND	ND	BL	BL	BL	ND	ND
DIBP	ND	ND	ND	BL	BL	BL	ND	ND
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A33	A34	A35	A36	B1	B2	B3	B4
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	ND
PBB	BL	BL	ND	---	ND	BL	---	---
PBDE	BL	BL	ND	---	ND	BL	---	---
DEHP	ND	ND	BL	---	BL	BL	---	---
BBP	ND	ND	BL	---	BL	BL	---	---
DBP	ND	ND	BL	---	BL	BL	---	---
DIBP	ND	ND	BL	---	BL	BL	---	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	B5
Pb	BL
Hg	BL
Cd	BL
Cr(VI)▼	BL
PBB	ND
PBDE	ND
DEHP	BL
BBP	BL
DBP	BL
DIBP	BL
Conclusion	PASS

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab. Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Notes:

(1) Interpretation of screening results by X-ray fluorescence spectrometry (XRF):

(a) Screening limits in mg/kg for regulated elements in various matrices according to IEC 62321-3-1:2013 Annex A as below table.

Element	Polymers	Metals	Composite Materials
Cd	BL≤(70-3σ)<X<(130+3σ)≤OL	BL≤(70-3σ)<X<(130+3σ)≤OL	LOD<X<(150+3σ)≤OL
Pb	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Hg	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Br	BL ≤ (300-3σ)< X	Not applicable	BL ≤ (250-3σ)< X
Cr	BL ≤ (700-3σ)< X	BL ≤ (700-3σ)< X	BL ≤ (500-3σ)< X

(b) If the maximum allowed level restricts PBB/PBDE and Cr(VI) rather than Br and Cr, the exceptions are the XRF determinations of Br and Cr. If the quantitative results for the elements Br and/or Cr are higher than the limit (for Br calculated based on the stoichiometry of Br in the most common congeners of PBB/PBDE), the sample is “inconclusive”.

(c) Results are obtained by EDXRF for primary screening, LOD = Limit of Detection, BL = Below Limit, OL= Over Limit, IN (The symbol X marks the region)=Inconclusive, where further investigation is necessary, and further chemical testing by ICP-OES (for Cd, Pb, Hg), UV-Vis (for Cr(VI)) and GC-MS (for PBB/PBDE) are recommended to be performed.

(d) The EDXRF screening test for elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

(2) Screening results of Phthalates (PHTH) below the limits are shown as "BL". Further chemical testing by GC-MS is to be performed if the results exceed limits.

Test Items	CAS No.
Bis(2-ethylhexyl) phthalate (DEHP)	117-81-7
Butyl benzyl phthalate (BBP)	85-68-7
Dibutyl phthalate (DBP)	84-74-2
Diisobutyl phthalate (DIBP)	84-69-5

(3) Interpretation of results by chemical tests:

(a) mg/kg = 0.0001%, MDL=Method detection Limit, ND = Not Detected (<MDL), --- = Not Applicable.

(b) Unit and MDL in wet chemical test

Test Items	Pb	Hg	Cd	DEHP	BBP	DBP	DIBP
Unit	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
MDL	10	10	10	100	100	100	100

The MDL for single compound of PBB and PBDE is 100 mg/kg,
MDL of Cr(VI) for polymer, composite and leather sample is 10 mg/kg.
MDL of Cr(VI) for metal sample is 0.10 μg/cm^2.

(c) ▼ =Metal sample

a. The sample is positive for Cr(VI) if the Cr(VI) concentration is greater than 0.13 μg/cm^2. The sample coating is considered to contain Cr(VI).

b. The sample is negative for Cr(VI) if Cr(VI) is ND (concentration less than 0.10 μg/cm^2). The coating is considered a non-Cr(VI) based coating

c. The result between 0.10 μg/cm^2 and 0.13 μg/cm^2 is considered to be inconclusive-unavoidable coating variations may influence the determination

Information on storage conditions and production date of the tested sample is unavailable and thus Cr(VI) results represent status of the sample at the time of testing.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

(4) Restricted substances and maximum concentration values tolerated by weight in homogeneous materials under RoHS Directive: Cd: 0.01%, Pb/Hg/Cr(VI)/PBB/PBDE/DEHP/BBP/DBP/DIBP: 0.1%. The limit is quoted from RoHS Directive (EU) 2015/863.

(5) IEC 62321 series is equivalent to EN 62321 series.

(6) According to the declaration from applicant, the materials of other parts in Model “E08T236-FW” are the same as those in Model “E08T228-FW”, and the results of Model “E08T228-FW” for support the results of other parts in Model “E08T236-FW”. The applicant will take the responsibility of all discrepancy and risk.

(7) According to the declaration from applicant, the materials of Model “E08T228-FW” are the same as those in Model mentioned in Client Ref. Information and its results for support the results of Model mentioned in Client Ref. Information. The applicant will take the responsibility of all discrepancy and risk.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区，5区 sgs.china@sgs.com


Member of the SGS Group (SGS SA)


Sample photos:





E08T228-FW














通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com












E08T236-FW



SGS authenticate the photo on original report only

*** End of Report ***

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国 · 浙江 · 宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Member of the SGS Group (SGS SA)