Verification Report

No.: NGBEC26003496901 **Date:** Jun 24, 2026

Client Name: ZHEJIANG TOT ELECTRIC CO.,LTD.

Client Address: NO.1, DEXIAN ROAD, CHENGNAN INDUSTRIAL ZONE, DONGHUA STREET, LONGYOU COUNTY, ZHEJIANG PROVINCE

Sample Name: Flush-type switch

Tested Basic Model No.: E08D103-FW

Tested Extended Model No.: F08D103

Client Ref. Information: abD101cd,abD102cd,abD103cd；
(ab=E01,E02,E03,E05,E06,E07,E08,E09,E10,E11,E12,E13,E14,E15,E16,E17,F01,F02,F02,F03,F04,F05,F06,F07,F08,F09,F10;
E01,E02,E03,E07,E08,E11,E12,E13,E14,E15,E16,E17,F01,F02,F03,F04,F05,F06,F07,F08,F09,F10 indicate white PC panel; E05, E09 indicateglass panel; E06, E10 indicate Aluminum panel; cd=blankor-SL,-BK,-CG,-SG, -BL, -BR, -WH, -RD,-MO, -CH, -IV,-GR,-BE,-FW,-FBK,-FBL,-FSL,-FBR,-FCG,-FSG,-FMK,-FSA,-FCR,-FTI,-FGU,-FPA,-MSL,-MBK,-MCG,-MBR,-MSG,-MRD,-GMO,-GCH,-GBE,-GWH,-GBK,-GCG,-GBL,-GSG-GRD: it indicates different color

The above sample(s) and information were provided by the client.

SGS Job No.: NBP26-003558

Sample Receiving Date: May 06, 2026

Verification Period: May 06, 2026 ~ Jun 22, 2026

Verification Requested: With reference to RoHS Directive (EU) 2015/863 amending 2011/65/EU.

Verification Method(s): Please refer to next page(s).

Verification Result(s): Please refer to next page(s).

Test Result Summary:

Test Items	Conclusion
EU RoHS Directive (EU) 2015/863 amending Annex II to Directive 2011/65/EU - Lead, Mercury, Cadmium, Hexavalent chromium, Polybrominated biphenyls (PBB), Polybrominated diphenyl ethers (PBDE), Bis(2-ethylhexyl) phthalate (DEHP), Butyl benzyl phthalate (BBP), Dibutyl phthalate (DBP) and Diisobutyl phthalate (DIBP)	Pass

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Hedy Hu
Approved Signatory

Scan to see the report


83B81E9E

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Laboratory


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国 · 浙江 · 宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，006幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Photo of Submitted Sample



E08D103-FW



F08D103

Verification Method(s):

1. With reference to IEC 62321-2:2021, disassembly and disjointment were performed for the submitted samples.
2. With reference to IEC 62321-1:2013, tests were performed for the samples indicated by the photos in this report.
   (1) With reference to IEC 62321-3-1:2013, screening by EDXRF spectroscopy.
   (2) Wet chemical test method: With reference to IEC 62321-4:2013+A1:2017, IEC62321-5:2013, IEC

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab (NCH)

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

62321-7-1:2015, IEC 62321-7-2:2017, IEC 62321-12:2023, IEC 62321-6:2015 and IEC62321-8:2017 , analyzed by ICP-OES,UV-Vis and GC-MS.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Verification Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0034969-0001.C001	E08D103-FW-White plastic
SN2	A2	NGB26-0034969-0001.C002	E08D103-FW-White plastic
SN3	A3	NGB26-0034969-0001.C003	E08D103-FW-White plastic
SN4	A4	NGB26-0034969-0001.C004	E08D103-FW-Silvery metal
SN5	A5	NGB26-0034969-0001.C005	E08D103-FW-Silvery metal
SN6	A6	NGB26-0034969-0001.C006	E08D103-FW-Silvery metal
SN7	A7	NGB26-0034969-0001.C007	E08D103-FW-Gray plastic
SN8	A8	NGB26-0034969-0001.C008	E08D103-FW-Silvery metal
SN9	A9	NGB26-0034969-0001.C009	E08D103-FW-Silvery metal
SN10	A10	NGB26-0034969-0001.C010	E08D103-FW-Silvery metal
SN11	A11	NGB26-0034969-0001.C011	E08D103-FW-Silvery metal
SN12	A12	NGB26-0034969-0001.C012	E08D103-FW-Silvery metal
SN13	A13.2	NGB26-0034969-0001.C013.C002	E08D103-FW-Silvery metal (A13 improved sample submitted by 2026-6-15)
SN14	A14	NGB26-0034969-0001.C014	E08D103-FW-Golden metal
SN15	A15	NGB26-0034969-0001.C015	E08D103-FW-Golden metal
SN16	A16	NGB26-0034969-0001.C016	E08D103-FW-Black audion body
SN17	A17	NGB26-0034969-0001.C017	E08D103-FW-Black audion body
SN18	A18	NGB26-0034969-0001.C018	E08D103-FW-Black plastic
SN19	A19	NGB26-0034969-0001.C019	E08D103-FW-Black plastic
SN20	A20	NGB26-0034969-0001.C020	E08D103-FW-White plastic
SN21	A21	NGB26-0034969-0001.C021	E08D103-FW-Brown plastic
SN22	A22	NGB26-0034969-0001.C022	E08D103-FW-Silvery metal
SN23	A23	NGB26-0034969-0001.C023	E08D103-FW-Semitransparent plastic
SN24	A24	NGB26-0034969-0001.C024	E08D103-FW-Silvery metal
SN25	A25	NGB26-0034969-0001.C025	E08D103-FW-Silvery metal
SN26	A26	NGB26-0034969-0001.C026	E08D103-FW-Green PCB body
SN27	A27.1	NGB26-0034969-0001.C027.C001	E08D103-FW-Silvery metal soldering tin (A27 improved sample submitted by 2026-6-12)
SN28	B1	NGB26-0034969-0002.C001	F08D103-White plastic
SN29	B2	NGB26-0034969-0002.C002	F08D103-White plastic
SN30	B3	NGB26-0034969-0002.C003	F08D103-White plastic
SN31	B4	NGB26-0034969-0002.C004	F08D103-White plastic

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Verification Result(s):

In accordance with the result of material risk assessment, the following disjointed parts in the submitted sample have been verified. (Unless otherwise specified, the unit is mg/kg).

Test Item(s)	A1	A2	A3	A4	A5	A6	A7	A8
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	ND	ND	ND	BL	BL
PBB	ND	ND	ND	---	---	---	ND	---
PBDE	ND	ND	ND	---	---	---	ND	---
DEHP	BL	BL	BL	---	---	---	BL	---
BBP	BL	BL	BL	---	---	---	BL	---
DBP	BL	BL	BL	---	---	---	BL	---
DIBP	BL	BL	BL	---	---	---	BL	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A9	A10	A11	A12	A13.2	A14	A15	A16
Pb	BL	BL	BL	BL	BL	26961▲	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	ND	ND	BL	BL	BL
PBB	---	---	---	---	---	---	---	ND
PBDE	---	---	---	---	---	---	---	ND
DEHP	---	---	---	---	---	---	---	BL
BBP	---	---	---	---	---	---	---	BL
DBP	---	---	---	---	---	---	---	BL
DIBP	---	---	---	---	---	---	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A17	A18	A19	A20	A21	A22	A23	A24
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	ND	ND	BL	BL	---	BL	---
PBDE	BL	ND	ND	BL	BL	---	BL	---
DEHP	ND	BL	BL	BL	BL	---	ND	---
BBP	ND	BL	BL	BL	BL	---	ND	---
DBP	ND	BL	BL	BL	BL	---	ND	---
DIBP	ND	BL	BL	BL	BL	---	ND	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A25	A26	A27.1	B1	B2	B3	B4
Pb	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区，5区 sgs.china@sgs.com

Test Item(s)	A25	A26	A27.1	B1	B2	B3	B4
PBB	---	BL	---	BL	BL	BL	BL
PBDE	---	BL	---	BL	BL	BL	BL
DEHP	---	BL	---	BL	BL	BL	BL
BBP	---	BL	---	BL	BL	BL	BL
DBP	---	BL	---	BL	BL	BL	BL
DIBP	---	BL	---	BL	BL	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Central Chemical Lab (CCL)
Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Notes:

(1) Interpretation of screening results by X-ray fluorescence spectrometry (XRF):

(a) Screening limits in mg/kg for regulated elements in various matrices according to IEC 62321-3-1:2013 Annex A as below table.

Element	Polymers	Metals	Composite Materials
Cd	BL≤(70-3σ)<X<(130+3σ)≤OL	BL≤(70-3σ)<X<(130+3σ)≤OL	LOD<X<(150+3σ)≤OL
Pb	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Hg	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Br	BL ≤ (300-3σ)< X	Not applicable	BL ≤ (250-3σ)< X
Cr	BL ≤ (700-3σ)< X	BL ≤ (700-3σ)< X	BL ≤ (500-3σ)< X

(b) If the maximum allowed level restricts PBB/PBDE and Cr(VI) rather than Br and Cr, the exceptions are the XRF determinations of Br and Cr. If the quantitative results for the elements Br and/or Cr are higher than the limit (for Br calculated based on the stoichiometry of Br in the most common congeners of PBB/PBDE), the sample is “inconclusive”.

(c) Results are obtained by EDXRF for primary screening, LOD = Limit of Detection, BL = Below Limit, OL= Over Limit, IN (The symbol X marks the region)=Inconclusive, where further investigation is necessary, and further chemical testing by ICP-OES (for Cd, Pb, Hg), UV-Vis (for Cr(VI)) and GC-MS (for PBB/PBDE) are recommended to be performed.

(d) The EDXRF screening test for elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

(2) Screening results of Phthalates (PHTH) below the limits are shown as "BL". Further chemical testing by GC-MS is to be performed if the results exceed limits.

Test Items	CAS No.
Bis(2-ethylhexyl) phthalate (DEHP)	117-81-7
Butyl benzyl phthalate (BBP)	85-68-7
Dibutyl phthalate (DBP)	84-74-2
Diisobutyl phthalate (DIBP)	84-69-5

(3) Interpretation of results by chemical tests:

(a) mg/kg = 0.0001%, MDL=Method detection Limit, ND = Not Detected (<MDL), --- = Not Applicable.

(b) Unit and MDL in wet chemical test

Test Items	Pb	Hg	Cd	DEHP	BBP	DBP	DIBP
Unit	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
MDL	10	10	10	100	100	100	100

The MDL for single compound of PBB and PBDE is 100 mg/kg,
MDL of Cr(VI) for polymer, composite and leather sample is 10 mg/kg.
MDL of Cr(VI) for metal sample is 0.10 μg/cm^2.

(c) ▼ =Metal sample

a. The sample is positive for Cr(VI) if the Cr(VI) concentration is greater than 0.13 μg/cm^2. The sample coating is considered to contain Cr(VI).

b. The sample is negative for Cr(VI) if Cr(VI) is ND (concentration less than 0.10 μg/cm^2). The coating is considered a non-Cr(VI) based coating

c. The result between 0.10 μg/cm^2 and 0.13 μg/cm^2 is considered to be inconclusive-unavoidable coating variations may influence the determination

Information on storage conditions and production date of the tested sample is unavailable and thus Cr(VI) results represent status of the sample at the time of testing.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

(4) Restricted substances and maximum concentration values tolerated by weight in homogeneous materials under RoHS Directive: Cd: 0.01%, Pb/Hg/Cr(VI)/PBB/PBDE/DEHP/BBP/DBP/DIBP: 0.1%. The limit is quoted from RoHS Directive (EU) 2015/863.

(5) IEC 62321 series is equivalent to EN 62321 series.

(6) ▲=According to the declaration from the client, Lead (Pb) in sample A14 is exempted by EU RoHS directive 2011/65/EU based on |ANNEX III 6(c)|: Copper alloy containing up to 4 % lead by weight.
More information about exemption can be found via the following link:
https://rohs.sgsonline.com.cn/PDFLinks/en/RSTS-TP-037%20RoHS%20Exemption%20%28EN%29.pdf

(7) According to the declaration from applicant, the materials of other parts in Model “F08D103” are the same as those in Model “E08D103-FW”, and the results of Model “E08D103-FW” for support the results of other parts in Model “F08D103”. The applicant will take the responsibility of all discrepancy and risk.

(8) According to the declaration from applicant, the materials of Model “E08D103-FW” are the same as those in Model mentioned in Client Ref. Information and its results for support the results of Model mentioned in Client Ref. Information. The applicant will take the responsibility of all discrepancy and risk.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.


通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com


Member of the SGS Group (SGS SA)


Sample photos:





E08D103-FW















Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch
Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com















通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国 · 浙江 · 宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com



SGS authenticate the photo on original report only
*** End of Report ***

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com